

|                         |  |
|-------------------------|--|
| 1. Record Nr.           | UNINA9910458493103321  |
| Titolo                  | Sumatra-Andaman Islands earthquake and tsunami of December 26, 2004 [[electronic resource] ] : lifeline performance // edited by Carl Strand and John Masek ; sponsored by Technical Council on Lifeline Earthquake Engineering  |
| Pubbl/distr/stampa      | Reston, VA, : American Society of Civil Engineers, c2008   |
| ISBN                    | 0-7844-7210-6  |
| Descrizione fisica      | 1 online resource (357 p.)   |
| Collana                 | Monograph / Technical Council on Lifeline Earthquake Engineering ; ; no. 30  |
| Altri autori (Persone)  | StrandCarl L (Carl Ludvig)<br>MasekJohn Paul   |
| Disciplina              | 624.1762095  |
| Soggetti                | Lifeline earthquake engineering - Asia<br>Tsunami damage - Asia<br>Public utilities - Asia<br>Transportation - Asia<br>Sumatra Earthquake, 2004<br>Nicobar Islands Earthquake, 2004<br>Indian Ocean Tsunami, 2004<br>Electronic books.   |
| Lingua di pubblicazione | Inglese  |
| Formato                 | Materiale a stampa   |
| Livello bibliografico   | Monografia   |
| Note generali           | "ICE, Institution of Civil Engineers."<br>"August 2007."   |
| Nota di bibliografia    | Includes bibliographical references.   |
| Nota di contenuto       | ""Table of Contents""; ""Acknowledgments""; ""SECTION 1: Introduction""; ""1.1 Overview""; ""1.1.1 Investigation Team""; ""1.2 Sri Lanka""; ""1.2.1 Investigation Team for Sri Lanka""; ""1.3 South India Peninsula""; ""1.1.1 Investigation Team for the South India Peninsula""; ""1.4 Thailand""; ""1.4.1 Thailand Investigation Team""; ""1.5 Andaman and Nicobar Islands""; ""1.5.1 Andaman and Nicobar Islands Investigation Team""; ""SECTION 2: Geoscience and Tsunami Generation""; ""Geoscience and Tsunami Generation""; ""2.1 Introduction""; ""2.1.1 Seismotectonic Setting""<br>""2.1.2 Region near Source Zone""""2.1.3 Probabilistic Seismic Hazard Map""; ""2.1.4 Recent Great Subduction-zone Earthquakes""; ""2.1.5 |

Fault Rupture"; "2.1.6 Seismic Ground Motions"; "2.1.7 Earthquake Intensity"; "2.1.8 March 28, 2005 Earthquake"; "2.1.9 Research Efforts"; "2.1.10 Geoscience Observations"; "2.2 Geoscience and Tsunami Specific to the South India Peninsula"; "2.2.1 Overview of System Performance"; "2.2.3 Damage Sites"; "2.2.4 Observations"; "2.3 Geoscience and Tsunami Aspects Specific to the Andaman and Nicobar Islands"

"SECTION 3: Roadway Transportation Systems""3.1 Sri Lanka"; "3.1.1 Roads and Bridges"; "3.1.2 Emergency Ferry Service"; "3.1.3 Bus Service"; "3.2 Roadway Transportation Systems in the South India Peninsula"; "3.2.1 Introduction"; "3.2.2 Locations of Damage"; "3.3 Roadway Transportation Systems in Thailand"; "3.3.1 Roadways"; "3.3.2 Bridges"; "3.3.3 Observations and Recommendations"; "3.4 Roadway Transportation Systems on Andaman and Nicobar Islands"; "3.4.1 Description of System"; "3.4.2 Overview of System Performance"; "3.4.3 Locations of Damage"

"3.4.4 Observations and Recommendations""SECTION 4: Electrical Power Systems"; "4.1 Electrical Power Systemsa€?Sri Lanka"; "4.1.1 Power System Damage"; "4.1.2 Power System Recovery"; "4.1.3 Power System Lessons Learned"; "4.2 Electric Power Systemsa€?South India Peninsula"; "4.2.1 Power System Damage"; "4.2.2 Power System Recovery"; "4.2.3 Power System Lessons Learned"; "4.2.4 Acknowledgements"; "4.3 Electrical Power Systemsa€?Thailand"; "4.3.1 Observations and Recommendations"; "4.4 Electrical Power Systemsa€?Andaman and Nicobar Islands"

"4.4.1 Overview of System Performance""4.4.2 Transmission Line Failure, New Haddo Wharf, Port Blair, South Andaman Island"; "4.4.3 Bamboo Flat (Phoenix Bay) 20-MW Power-Plant Failure, South Andaman Island"; "4.4.4 Kalpong Hydroelectric Power Plant Failure near Diglipur, North Andaman Island"; "4.4.5 Transmission Tower Failure at Middle Strait"; "4.4.6 Middle Andaman Islands"; "4.4.7 Southern Islands"; "4.4.8 Major Observations and Recommendations";

"SECTION 5: Water Systems"; "5.1 Water Systemsa€?Sri Lanka"; "5.2 Water Systemsa€?South India Peninsula"

"5.2.1 Locations of Damage"

---