

1. Record Nr.	UNINA9910462679503321
Titolo	Chile earthquake of 2010 lifeline performance [[electronic resource] /] / prepared by Earthquake Investigation Committee of the Technical Council of Lifeline Earthquake Engineering ; edited by Alex K. Tang, John M. Eidinger ; sponsored by Technical Council on Lifeline Earthquake Engineering
Pubbl/distr/stampa	Reston, Va., : American Society of Civil Engineers, 2013
ISBN	0-7844-7784-1
Descrizione fisica	1 online resource (425 p.)
Collana	Monograph ; ; no. 36
Altri autori (Persone)	TangAlex EidingerJohn M
Disciplina	624.1/762
Soggetti	Lifeline earthquake engineering - Chile - Evaluation Earthquake damage - Chile Chile Earthquake, Chile, 2010 (February 27) Electronic books.
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	Description based upon print version of record.
Nota di bibliografia	Includes bibliographical references and index.
Nota di contenuto	""Cover""; ""Contents""; ""Preface""; ""Contributors""; ""Acknowledgements""; ""Acknowledgment of Local Support""; ""1. INTRODUCTION""; ""1.1 Geotechnical Aspects""; ""1.2 Lifelines""; ""1.3 Organization""; ""2. SEISMOLOGY AND GEOTECHNICAL CONSIDERATIONS""; ""2.1 Geologic Aspects""; ""2.2 Geotechnical Engineering Aspects""; ""2.3 Discussion and Recommendations""; ""2.4 Acknowledgements""; ""2.5 References""; ""3. TRANSPORTATION SYSTEMS""; ""3.1 Description of the System""; ""3.2 Overview of System Performance""; ""3.3 Performance of Highways and Bridges""; ""3.4 Railways"" ""3.5 Observations and Recommendations""; ""3.6 Acknowledgements""; ""3.7 References""; ""4. PORTS""; ""4.1 Overview of Ports Performance""; ""4.2 Coronel""; ""4.3 Port of San Vincente""; ""4.4 Port of Lirquen""; ""4.5 Port of Talcahuano""; ""4.6 Navy Port at Molo""; ""4.7 Abastible Pier and Other Independent Offshore Piers in the Concepcion Area""; ""4.8 Major Observations and Recommendations""; ""4.9

Acknowledgements"; ""5. GAS AND LIQUID FUEL"; ""5.1 Description of System"; ""5.2 Refinery Performance"; ""5.3 Crude Oil Pipeline System Performance"
""5.4 Liquid Petroleum Gas (LPG) Plant Performance""""5.5 Gas Fuel System Performance"; ""5.6 Major Observations and Recommendations"; ""5.7 Acknowledgments"; ""6. ELECTRIC POWER SYSTEMS"; ""6.1 System Description"; ""6.2 System Characteristics and Response"; ""6.3 Generating Systems"; ""6.4 Transmission System"; ""6.5 Distribution System"; ""6.6 Transmission and Distribution Lines"; ""6.7 Conclusions and Observations"; ""6.8 Acknowledgements"; ""6.9 References"; ""7. TELECOMMUNICATION SYSTEMS"; ""7.1 Description of the System"; ""7.2 Overview of System Performance""
""7.3 Cellular Networks""""7.4 Landline Network Including Transmission and Distribution"; ""7.5 General Observations"; ""7.6 Major Observations and Recommendations"; ""7.7 Acknowledgements"; ""8. WATER AND WASTEWATER SYSTEM"; ""8.1 Description of System"; ""8.2 Overview of System Performance"; ""8.3 Damage Sites"; ""8.4 Major Observations and Recommendations"; ""8.5 Acknowledgments"; ""8.6 References"; ""9. AIRPORTS"; ""9.1 Description of Airports"; ""9.2 Overview of System Performance"; ""9.3 Santiago Internatioanl Airport (SCL)""
""9.4 ConcepcióA3n International Airport (CCP)""""9.5 Los Angeles Airport (LSQ)"; ""9.6 Observations and Recommendations"; ""9.7 Acknowledgments"; ""10. INFRASTRUCTURE INTERDEPENDENCIES AND RESILIENCE"; ""10.1 Phases of Lifeline System Interdependence"; ""10.2 Lifeline System Restoration Performance"; ""10.3 Quantitative Lifeline Interdependence Analysis"; ""10.4 Research and Practical Challenges"; ""10.5 Conclusions and Recommendations"; ""10.6 Acknowledgements"; ""10.7 References"; ""10.8 Appendix A""; ""11. EMERGENCY RESPONSE, RECOVERY, AND SOCIAL IMPACT""
""11.1 Earthquake Culture""
