

1. Record Nr.	UNINA9910464298103321
Titolo	Guideline for condition assessment of the building envelope // American Society of Civil Engineers
Pubbl/distr/stampa	Reston, Virginia : , : American Society of Civil Engineers, , 2014 ©2014
ISBN	0-7844-7827-9
Descrizione fisica	1 online resource (46 p.)
Collana	ASCE Standard ASCE/SEI ; ; 30-14
Disciplina	690/.12
Soggetti	Exterior walls - Evaluation - Standards Building inspection - Standards Electronic books.
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	"This document uses both the International System of Units (SI) and customary units."
Nota di bibliografia	Includes bibliographical references at the end of each chapters and index.
Nota di contenuto	""CONTENTS""; ""STANDARDS""; ""FOREWORD""; ""ACKNOWLEDGMENTS""; ""1 General""; ""1.1 Scope and Intent""; ""1.2 Purpose of Assessment""; ""1.3 Types of Assessment""; ""1.3.1 Cursory Assessment""; ""1.3.2 Preliminary Assessment""; ""1.3.3 Detailed Assessment""; ""1.4 Safety""; ""1.5 Qualifications and Equipment""; ""1.5.1 Personnel Qualifications""; ""1.5.2 Equipment""; ""1.6 Agreements""; ""1.6.1 Services""; ""1.6.2 Compensation""; ""1.6.3 Authority and Accessibility""; ""1.6.4 Liability""; ""1.6.5 Agreements or Contracts""; ""1.6.6 Legal Obligations""; ""1.7 Definitions"" ""2 Building Envelope Systems, Component Features, and Materials"" ""2.1 Introduction""; ""2.2 Building Envelope System Categories""; ""2.3 Roof Systems""; ""2.3.1 Low Slope Systems""; ""2.3.2 Steep Slope Systems""; ""2.4 Wall Systems""; ""2.4.1 Unreinforced Concrete""; ""2.4.2 Reinforced Concrete""; ""2.4.3 Precast Concrete""; ""2.4.4 Unreinforced Masonry""; ""2.4.5 Reinforced Masonry""; ""2.4.6 Unreinforced Masonry Cavity Wall""; ""2.4.7 Reinforced Masonry Cavity Wall""; ""2.4.8 Masonry Veneer with Wood or Steel Stud Backup""; ""2.4.9 Siding Systems with Wood or Steel Stud Backup"" ""2.4.10 Architectural Precast Concrete"" ""2.4.11 Glass Fiber Reinforced

Concrete Panel"; "2.4.12 Aluminum Frame Curtain Wall"; "2.4.13 Interlocking Metal Panel Wall"; "2.4.14 Thin Stone Veneer Panel"; "2.4.15 Prefabricated Masonry Panels"; "2.5 Fenestration Systems"; "2.6 Building Appendages"; "2.7 Foundation Wall Systems"; "2.7.1 Cast-in-Place Concrete"; "2.7.2 Masonry"; "2.7.3 Wood"; "2.7.4 Waterproofing Systems"; "2.7.5 Drainage Systems"; "2.8 Deck Waterproofing Systems"; "2.8.1 Exposed Membrane Systems"; "2.8.2 Protected Membrane Systems"; "2.9 Underground Structures"; "2.10 Fabric Structures"; "2.11 Intersections and Terminations"; "2.12 System Component Features"; "2.12.1 Acoustical Resistance"; "2.12.2 Aesthetic Treatment"; "2.12.3 Air Infiltration"; "2.12.4 Condensation Control"; "2.12.5 Durability"; "2.12.6 Fire Resistance"; "2.12.7 Historic Significance"; "2.12.8 Interface Compatibility"; "2.12.9 Movement Control"; "2.12.10 Natural Light and Ventilation"; "2.12.11 Security"; "2.12.12 Serviceability"; "2.12.13 Solar Heat Gain"; "2.12.14 Strength"; "2.12.15 Thermal Resistance"; "2.12.16 Water Infiltration"; "2.12.17 Wildlife, Insect, and Organism Resistance"; "3 Condition Assessment Procedure"; "3.1 General Approach"; "3.2 cursory Condition Assessment"; "3.3 Definition of Scope"; "3.4 Preliminary Condition Assessment"; "3.4.1 Document Review"; "3.4.2 General Observations"; "3.4.3 Interviews with Involved Parties"; "3.4.4 Identification of Typical Problem Areas"; "3.5 Preliminary Report"; "3.5.1 Preliminary Findings"; "3.5.2 Identification of Legal and/or Code Compliance Issues"; "3.5.3 Preliminary Conclusions"; "3.5.4 Preliminary Recommendations"

---