

1. Record Nr.	UNINA9910699663903321
Titolo	Failure of steam dryer cover plate after a recent power uprate [[electronic resource]]
Pubbl/distr/stampa	Washington, DC, : U.S. Nuclear Regulatory Commission, Office of Nuclear Reactor Regulation, [2002-2004]
Descrizione fisica	1 online resource (2, 2, 4, 1 page)
Collana	NRC information notice ; ; 2002-26
Soggetti	Boiling water reactors - Piping Transients (Electricity) Nuclear pressure vessels - Defects
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	Title from PDF title screen (viewed on Sept. 29, 2010). "September 11, 2002." "ML022530291." Includes supplement 1, ML031980434, dated July 21, 2003, and supplement 2, ML040080392, dated January 9, 2004.