

1. Record Nr.	UNINA9910703429003321
Titolo	Failure of pump shaft coupling caused by temper embrittlement during manufacture
Pubbl/distr/stampa	Washington, D.C. : , : United States Nuclear Regulatory Commission, Office of Nuclear Reactor Regulation, , [1993]
Descrizione fisica	1 online resource
Collana	NRC information notice ; ; 93-68
Soggetti	Nuclear facilities - United States - Equipment and supplies Feed-water pumps - Defects
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	Title from title screen (viewed on Jan. 5, 2014). "September 1, 1993."