

1. Record Nr.	UNINA9911020254903321
Autore	Proverbs David G
Titolo	Flood damaged property : a guide to repair // David G. Proverbs and Robby Soetanto
Pubbl/distr/stampa	Oxford, OX, UK ; ; Malden, MA, USA, : Blackwell Pub., 2004
ISBN	9786610213061 9781280213069 128021306X 9780470798508 0470798505 9780470759295 0470759291 9781405148061 1405148063
Descrizione fisica	1 online resource (242 p.)
Altri autori (Persone)	SoetantoRobby
Disciplina	690/.24
Soggetti	Flood damage - Risk assessment
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	Description based upon print version of record.
Nota di bibliografia	Includes bibliographical references (p. 216-219) and index.
Nota di contenuto	Contents; Preface; Acknowledgements; 1 Introduction to Flooding; 1.1 Introduction; 1.2 Autumn 2000 floods; 1.3 Ownership and responsibilities; 1.4 Damage caused by flooding; 1.5 Flood damage to domestic properties; 1.6 Organisation of this book; 2 Preparing for a Flood; 2.1 Introduction; 2.2 Flood risk; 2.3 Causes and effects of flooding; 2.4 Flood protection; 2.5 Flood resilient repairs; 2.6 Summary; 3 Flood Characteristics; 3.1 Introduction; 3.2 Flood damage function; 3.3 The importance of flood characteristics; 3.4 Sources of information or methods to determine flood characteristics; 3.5 Summary; 4 Drying Out Flooded Buildings; 4.1 Introduction; 4.2 Background information; 4.3 Methods and/or equipment employed to dry flood damaged buildings; 4.4 Sealing off sections of the building to assist drying; 4.5 Methods and/or equipment employed to determine if a building is sufficiently dry for repair works to commence; 4.6 Summary; 5 Reinstatement of Flood Damaged Floors; 5.1 Introduction;

5.2 Methodology; 5.3 Results and discussion; 5.3.1 Scenario 1: 'The dwelling has vinyl floor tiles installed that have been submerged by floodwater'  
5.3.2 Scenario 2: 'The dwelling has a vinyl sheet floor covering installed that has been submerged by floodwater'  
5.3.3 Scenario 3: 'The dwelling has a quarry tiled floor which has been submerged by floodwater';  
5.3.4 Scenario 4: 'The dwelling has a solid concrete floor which has been submerged by floodwater'; 5.3.5 Scenario 5: 'The dwelling has a suspended timber (chipboard) floor which has been submerged by floodwater'; 5.3.6 Scenario 6: 'The dwelling has a suspended timber (chipboard) floor with tongued and grooved floorboards'  
5.3.7 Scenario 7: 'When the floorboards are removed, it is discovered that the sleeper walls are constructed directly off the ground (i.e. no concrete slab has been included)'  
5.3.8 Scenario 8: 'The dwelling has a concrete floor which has been covered with solid oak blocks'; 5.4 Summary; 6 Reinstatement of Flood Damaged Walls; 6.1 Introduction; 6.2 Results and discussion; 6.2.1 Scenario 9: 'The external wall of the property is brickwork with cement mortal joints'; 6.2.2 Scenario 10: 'The external wall of the property has a rendered finish'  
6.2.3 Scenario 11: 'The external wall of the property has a pebbledash finish'  
6.2.4 Scenario 12: 'An internal wall of the flood damaged property is constructed of brickwork with a paint finish applied directly to it'; 6.2.5 Scenario 13: 'An internal wall of the flood damaged property has been covered with ceramic tiles'; 6.2.6 Scenario 14: 'An internal wall of the flood damaged property has been covered with a wood veneer on timber grounds'; 6.2.7 Scenario 15: 'An internal wall of the flood damaged property has been decorated with wallpaper'  
6.2.8 Scenario 16: 'An external wall of a flood damaged property has evidence of a rising damp problem'

---

## Sommario/riassunto

With climate change and the development of property on flood plains, the flooding of buildings has become a considerable problem, both for property owners and their insurers. This book, based on extensive research, provides guidance on how to assess and repair flood damaged properties.

---