

1. Record Nr.	UNINA9910689951103321
Titolo	Pilot precautions and procedures to be taken in preventing aircraft reciprocating engine induction system and fuel system icing problems [[electronic resource]]
Pubbl/distr/stampa	Washington, D.C. : , : Dept. of Transportation, Federal Aviation Administration, , [1981]
Descrizione fisica	6 pages : digital, PDF file
Collana	Advisory circular ; ; AC 20-113
Soggetti	Airplanes - Ice prevention - United States Aeronautics - United States - Safety measures
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	This Advisory Circular cancels AC 60-9 and 20-92. "10/22/81." Title from PDF file caption (viewed Oct. 15, 2008).