

| | |
|-------------------------|---|
| 1. Record Nr. | UNINA9910697081503321 |
| Autore | Grendahl Scott |
| Titolo | Failure analysis of a cracked CH-47 swashplate rotating ring, S/N BCW-1379 [[electronic resource] /] / Scott Grendahl, Russell Yocum |
| Pubbl/distr/stampa | Aberdeen Proving Ground, MD : , : Army Research Laboratory, , [2006] |
| Descrizione fisica | 1 online resource (iv, 22 pages) : color illustrations |
| Collana | ARL-TR ; ; 3826 |
| Altri autori (Persone) | YocumRussell |
| Soggetti | Chinook (Military transport helicopter) - Evaluation Chinook (Military transport helicopter) - Parts - Cracking - Evaluation Chinook (Military transport helicopter) - Accidents - United States - Prevention Metals - Fatigue - Testing Metals - Cracking - Evaluation |
| Lingua di pubblicazione | Inglese |
| Formato | Materiale a stampa |
| Livello bibliografico | Monografia |
| Note generali | Title from PDF t.p. (viewed June 14, 2010). "June 2006." |