

1. Record Nr.	UNINA9910697081703321
Autore	Grendahl Scott
Titolo	Failure analysis of a cracked UH-1 tailboom former, P/N 205-030-807-97 [[electronic resource] /] prepared by Scott Grendahl, Benjamin Hardisky and Russell Yocum for U.S. Army Aviation and Missile Command
Pubbl/distr/stampa	Aberdeen Proving Ground, MD : , : Army Research Laboratory, , [2006]
Descrizione fisica	1 online resource (vi, 22 pages) : color illustrations
Collana	ARL-TR ; ; 3828
Altri autori (Persone)	HardiskyBenjamin YocumRussell
Soggetti	UH-1 (Helicopter) - Parts - Cracking - Evaluation UH-1 (Helicopter) - Parts - Corrosion fatigue - Evaluation UH-1 (Helicopter) - Accidents - United States - Prevention Metals - Corrosion fatigue - Testing Metals - Cracking - Evaluation
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	Title from PDF t.p. (viewed June 14, 2010). "June 2006."