

1. Record Nr.	UNINA9910697094103321
Titolo	Shuttle gaseous hydrogen venting risk from flow control valve failure [[electronic resource] /] J. Philip Drummond ... [and others]
Pubbl/distr/stampa	Hampton, Va. : , : National Aeronautics and Space Administration, Langley Research Center, , [2009]
Descrizione fisica	1 online resource (34 pages) : illustrations (some color)
Collana	NASA/TM ; ; 2009-215942
Altri autori (Persone)	DrummondJ. Philip (John Philip)
Soggetti	Control valves Hydrogen Venting Aerospace safety Endeavour (orbiter) Risk management Failure analysis
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	Title from title screen (viewed on May 14, 2012). "October 2009."
Nota di bibliografia	Includes bibliographical references (pages 33-34).