

1. Record Nr.	UNINA9910699660803321
Titolo	Centrifugal charging pump thrust bearing damage not detected due to inadequate assessment of oil analysis results and selection of pump surveillance points [[electronic resource]]
Pubbl/distr/stampa	Washington, DC : , : U.S. Nuclear Regulatory Commission, Office of Nuclear Reactor Regulation, , [2001]
Descrizione fisica	1 online resource
Collana	NRC information notice ; ; 2001-06
Soggetti	Centrifugal pumps - Maintenance and repair Bearings (Machinery)
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	Title from HTML title screen (viewed on Sept. 30, 2010). "May 11, 2001."