

| | |
|-------------------------|--|
| 1. Record Nr. | UNINA9910699684703321 |
| Titolo | Inadequate test procedure fails to detect inoperable criticality accident alarm horns |
| Pubbl/distr/stampa | Washington, D.C. : , : U.S. Nuclear Regulatory Commission, Office of Nuclear Reactor Regulation : , : U.S. Nuclear Regulatory Commission, Office of Nuclear Material Safety and Safeguards, , [2005] |
| Descrizione fisica | 1 online resource (3, 3 pages) |
| Collana | NRC information notice ; ; 2005-28 |
| Soggetti | Nuclear facilities - Accidents - United States Radiation warning systems - Defects - United States Criticality (Nuclear engineering) Nuclear facilities - Accidents United States |
| Lingua di pubblicazione | Inglese |
| Formato | Materiale a stampa |
| Livello bibliografico | Monografia |
| Note generali | Title from PDF title screen (viewed on Sept. 17, 2010). "October 31, 2005." "ML052720579." |