

1. Record Nr.	UNINA9910701821303321
Titolo	Failure of turbine-driven main feedwater pump to trip because of contaminated oil [[electronic resource]]
Pubbl/distr/stampa	Washington, D.C. : , : U.S. Nuclear Regulatory Commission, Office of Nuclear Reactor Regulation, , [1993]
Descrizione fisica	1 online resource
Collana	NRC information notice ; ; 93-48
Soggetti	Feed-water pumps Lubrication and lubricants - Defects Nuclear power plants - Safety measures
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	Title from title screen (viewed June 20, 2012). "July 6, 1993."