

| | |
|-------------------------|--|
| 1. Record Nr. | UNINA9910706842603321 |
| Autore | Meyer William <1939-> |
| Titolo | The effects of ground water, slope stability, and seismic hazard on the stability of the South Fork Castle Creek blockage in the Mount St. Helens Area, Washington // by William Meyer [and three others] |
| Pubbl/distr/stampa | Washington : , : United States Department of the Interior, Geological Survey, , 1985 |
| Descrizione fisica | 1 online resource (iv, 42 pages) : illustrations, maps |
| Collana | U.S. Geological Survey professional paper ; ; 1345 |
| Soggetti | Landslides - Washington (State) - Castle Creek, South Fork Slopes (Soil mechanics) - Washington (State) - Castle Creek, South Fork Landslides Slopes (Soil mechanics) Saint Helens, Mount (Wash.) Eruption, 1980 Washington (State) Castle Creek, South Fork Washington (State) Mount Saint Helens |
| Lingua di pubblicazione | Inglese |
| Formato | Materiale a stampa |
| Livello bibliografico | Monografia |
| Nota di bibliografia | Includes bibliographical references (pages 41-42). |