

1. Record Nr.	UNINA9910715156603321
Titolo	Diaphragm failure in scram outlet valve causing rod insertion
Pubbl/distr/stampa	Washington, D.C. : , : United States Nuclear Regulatory Commission, Office of Nuclear Reactor Regulation, , 1986
Descrizione fisica	1 online resource
Collana	Information notice ; ; no. 86-109
Soggetti	Diaphragms (Mechanical devices) - Defects Nuclear power plants - Piping - Valves Nuclear fuel rods
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	"December 29, 1986."