

1. Record Nr.	UNINA9910716528703321
Titolo	Erroneous criticality alarm monitoring signal caused by incorrect data acquisition module configuration
Pubbl/distr/stampa	Washington, DC : , : United States. Nuclear Regulatory Commission, Office of Nuclear Material Safety and Safeguards, , 2011
Descrizione fisica	1 online resource (3 pages) : illustrations
Collana	NRC information notice ; ; 2011-06
Soggetti	Nuclear reactors - Reactivity - Safety measures False alarms
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	"March 22, 2011." "ML110340026."