

1. Record Nr.	UNINA9910716655803321
Titolo	Shield building concrete subsurface laminar cracking caused by moisture intrusion and freezing
Pubbl/distr/stampa	Washington, DC : , : United States Nuclear Regulatory Commission, Office of Nuclear Reactor Regulation : , : Office of New Reactors, , 2013
Descrizione fisica	1 online resource (5 pages)
Collana	NRC information notice ; ; 2013-04
Soggetti	Nuclear reactors - Containment Nuclear reactors - Materials - Cracking
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	"March 7, 2013." "ML12352A052."