

1. Record Nr.	UNINA9910555109503321
Autore	Greulich Owen R.
Titolo	Fabrication of metallic pressure vessels / / Owen R. Greulich, Maan H. Jawad
Pubbl/distr/stampa	Hoboken, New Jersey : , : Wiley : , : ASME Press, , [2022] ©2022
ISBN	1-119-67488-3 1-119-67487-5 1-119-67490-5
Descrizione fisica	1 online resource (333 pages)
Collana	Wiley-ASME Press series
Disciplina	681.76041
Soggetti	Pressure vessels - Design and construction Electronic books.
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Nota di bibliografia	Includes bibliographical references and index.
Nota di contenuto	Cover -- Title Page -- Copyright Page -- Contents -- Preface -- Acknowledgments -- Chapter 1 Introduction -- 1.1 Introduction -- 1.2 Fabrication Sequence -- 1.3 Cost Considerations -- 1.3.1 Types of costs -- 1.3.2 Design choices -- 1.3.3 Shipping -- 1.3.4 General approach to cost control -- 1.4 Fabrication of Nonnuclear Versus Nuclear Pressure Vessels -- 1.5 Units and Abbreviations -- 1.6 Summary -- Chapter 2 Materials of Construction -- 2.1 Introduction -- 2.2 Ferrous Alloys -- 2.2.1 Carbon steels (Mild steels) -- 2.2.2 Low alloy steels (Cr-Mo steels) -- 2.2.3 High alloy steels (stainless steels) -- 2.2.4 Cost of ferrous alloys -- 2.3 Nonferrous Alloys -- 2.3.1 Aluminum alloys -- 2.3.2 Copper alloys -- 2.3.3 Nickel alloys -- 2.3.4 Titanium alloys -- 2.3.5 Zirconium alloys -- 2.3.6 Tantalum alloys -- 2.3.7 Price of nonferrous alloys -- 2.4 Density of Some Ferrous and Nonferrous Alloys -- 2.5 Nonmetallic Vessels -- 2.6 Forms and Documentation -- 2.7 Miscellaneous Materials -- 2.7.1 Cast iron -- 2.7.2 Gaskets -- 2.7.2.1 Gasket types -- 2.7.2.2 Gasket containment -- References -- Chapter 3 Layout -- 3.1 Introduction -- 3.2 Applications -- 3.3 Tools and Their Use -- 3.4 Layout Basics -- 3.4.1 Projection -- 3.4.2 Triangulation -- 3.5 Material Thickness and

Bending Allowance -- 3.6 Angles and Channels -- 3.7 Marking Conventions -- 3.8 Future of Plate Layout -- Reference -- Chapter 4 Material Forming -- 4.1 Introduction -- 4.1.1 Bending versus three-dimensional forming -- 4.1.2 Other issues -- 4.1.3 Plastic Theory -- 4.1.4 Forming limits -- 4.1.5 Grain direction -- 4.1.6 Cold versus hot forming -- 4.1.7 Spring back -- 4.2 Brake Forming (Angles, Bump-Forming) -- 4.2.1 Types of dies -- 4.2.2 Brake work forming limits -- 4.2.3 Crimping -- 4.2.4 Bending of pipes and tubes -- 4.2.5 Brake forming loads -- 4.3 Roll Forming (Shells, Reinforcing Pads, Pipe/Tube).
4.3.1 Pyramid rolls -- 4.3.2 Pinch rolls -- 4.3.3 Two-roll systems -- 4.3.4 Rolling radius variability compensation -- 4.3.5 Heads and caps -- 4.3.6 Hot forming -- 4.4 Tolerances -- 4.4.1 Brake forming tolerances -- 4.4.2 Roll forming tolerances -- 4.4.3 Press forming tolerances -- 4.4.4 Flanging tolerances -- Reference -- Chapter 5 Fabrication -- 5.1 Introduction -- 5.2 Layout -- 5.3 Weld Preparation -- 5.3.1 Hand and automatic grinders -- 5.3.2 Nibblers -- 5.3.3 Flame cutting -- 5.3.4 Boring mills -- 5.3.5 Lathes -- 5.3.6 Routers -- 5.3.7 Other cutter arrangements -- 5.4 Forming -- 5.5 Vessel Fit Up and Assembly -- 5.5.1 The fitter -- 5.5.2 Fit up tools -- 5.5.3 Persuasion and other fit up techniques -- 5.5.4 Fixturing -- 5.5.5 Welding fit up -- 5.5.6 Weld shrinkage -- 5.5.7 Order of assembly -- 5.6 Welding -- 5.6.1 Welding position -- 5.6.2 Welding residual stresses -- 5.6.3 Welding positioners, turning rolls, column and boom weld manipulators -- 5.7 Correction of Distortion -- 5.8 Heat Treatment -- 5.8.1 Welding preheat -- 5.8.2 Interpass temperature -- 5.8.3 Post weld heat treatment -- 5.9 Post-fabrication Machining -- 5.10 Field Fabrication - Special Issues -- 5.10.1 Exposure to the elements -- 5.10.2 Staging area -- 5.10.3 Tool and equipment availability -- 5.10.4 Staffing -- 5.10.5 Material handling -- 5.10.6 Energy sources -- 5.10.7 PWHT -- 5.10.8 Layout -- 5.10.9 Fit up -- 5.10.10 Welding -- 5.11 Machining -- 5.12 Cold Springing -- Chapter 6 Cutting and Machining -- 6.1 Introduction -- 6.2 Common Cutting Operations for Pressure Vessels -- 6.3 Cutting Processes -- 6.3.1 Plate cutting -- 6.3.2 Pipe, bar, and structural shape cutting -- 6.4 Common Machining Functions and Processes -- 6.5 Common Machining Functions for Pressure Vessels -- 6.5.1 Weld preparation -- 6.5.2 Machining of flanges -- 6.5.3 Tubesheets -- 6.5.4 Heat exchanger channels. 6.5.5 Heat exchanger baffles -- 6.6 Setup Issues -- 6.7 Material Removal Rates -- 6.7.1 Feed -- 6.7.2 Speed -- 6.7.3 Depth of cut -- 6.8 Milling -- 6.9 Turning and Boring -- 6.10 Machining Centers -- 6.11 Drilling -- 6.12 Tapping -- 6.13 Water Jet Cutting -- 6.14 Laser Machining -- 6.15 Reaming -- 6.16 Electrical Discharge Machining, Plunge and Wire -- 6.17 Electrochemical Machining -- 6.18 Electron Beam Machining -- 6.19 Photochemical Machining -- 6.20 Ultrasonic Machining -- 6.21 Planing and Shaping -- 6.22 Broaching -- 6.23 3D Printing -- 6.24 Summary -- Reference -- Chapter 7 Welding -- 7.1 Introduction -- 7.2 Weld Details and Symbols -- 7.2.1 Single fillet welds -- 7.2.2 Double fillet welds -- 7.2.3 Intermittent fillet welds -- 7.2.4 Single-bevel butt welds -- 7.2.5 Double-bevel butt welds -- 7.2.6 J-groove or double J-groove welds -- 7.2.7 Backing strips -- 7.2.8 Consumables -- 7.2.9 Tube-to-tubesheet welds -- 7.2.10 Weld symbols -- 7.3 Weld Processes -- 7.3.1 Diffusion welding (DFW) -- 7.3.2 Electron beam welding (EBW) -- 7.3.3 Electrogas welding (EGW) -- 7.3.4 Electroslag welding (ESW) -- 7.3.5 Flux-cored arc welding (FCAW) -- 7.3.6 Flash welding -- 7.3.7 Friction stir welding (FSW) -- 7.3.8 Gas metal-arc welding (GMAW) -- 7.3.9 Gas tungsten-arc welding (GTAW) -- 7.3.10 Laser beam welding (LBW) -- 7.3.11 Orbital

welding -- 7.3.12 Oxyfuel gas welding (OFW) -- 7.3.13 Plasma-arc welding (PAW) -- 7.3.14 Resistance spot welding (RSW) -- 7.3.15 Resistance seam welding (RSEW) -- 7.3.16 Submerged-arc welding (SAW) -- 7.3.17 Shielded metal-arc welding (SMAW) -- 7.3.18 Stud welding -- 7.4 Weld Preheat and Interpass Temperature -- 7.5 Post Weld Heat Treating -- 7.6 Welding Procedures -- 7.7 Control of Residual Stress and Distortion -- 7.8 Material Handling to Facilitate Welding -- 7.9 Weld Repair -- 7.10 Brazing -- 7.10.1 Applications. 7.10.2 Filler metal -- 7.10.3 Heating -- 7.10.4 Flux -- 7.10.5 Brazing procedures -- Reference -- Chapter 8 Welding Procedures and Post Weld Heat Treatment -- 8.1 Introduction -- 8.2 Welding Procedures -- 8.3 Weld Preparation Special Requirements -- 8.4 Weld Joint Design and Process to Reduce Stress and Distortion -- 8.4.1 Reduced heat input -- 8.4.2 Lower temperature differential -- 8.4.3 Choice of weld process -- 8.4.4 Weld configuration and sequencing -- 8.5 Weld Preheat and Interpass Temperature -- 8.6 Welder Versus Welding Operator -- 8.6.1 Welders -- 8.6.2 Welding operators -- 8.6.3 Differences in qualifications -- 8.7 Weld Repair -- 8.7.1 Slag inclusion during welding -- 8.7.2 Surface indications after cooling of welds -- 8.7.3 Delayed hydrogen cracking after welding -- 8.7.4 Cracks occurring subsequent to PWHT -- 8.8 Post Weld Heat Treating -- 8.8.1 PWHT of carbon steels -- 8.8.2 PWHT of low alloy steels -- 8.8.3 Some general PWHT requirements for carbon steels and low alloy steels -- 8.8.4 PWHT of stainless steel -- 8.8.5 PWHT of nonferrous alloys -- 8.9 Cladding, Overlay, and Loose Liners -- 8.9.1 Cladding -- 8.9.2 Weld overlay -- 8.9.3 Loose liners -- 8.10 Brazing -- 8.10.1 Applications -- 8.10.2 Filler metal -- 8.10.3 Heating -- 8.10.4 Flux -- 8.10.5 Brazing procedures -- Reference -- Chapter 9 Fabrication of Pressure Equipment Having Unique Characteristics -- 9.1 Introduction -- 9.2 Heat Exchangers -- 9.2.1 U-tube heat exchangers -- 9.2.2 Fixed heat exchangers -- 9.2.3 Floating head heat exchangers -- 9.2.4 Attachment of tubes-to-tubesheets and tubes-to-headers -- 9.2.5 Expansion joints -- 9.2.6 Assembly of heat exchangers -- 9.3 Dimpled Jackets -- 9.4 Layered Vessels -- 9.4.1 Introduction -- 9.4.2 Fabrication of layered shells -- 9.5 Rectangular Vessels -- 9.6 Vessels with Refractory and Insulation -- 9.7 Vessel Supports -- 9.8 Summary. References -- Chapter 10 Surface Finishes -- 10.1 Introduction -- 10.2 Types of Surface Finishes -- 10.2.1 Surface characteristics, unfinished -- 10.2.2 Passivation -- 10.2.3 Applied coatings -- Reference -- Chapter 11 Handling and Transportation -- 11.1 Introduction -- 11.2 Handling of Vessels and Vessel Components Within the Fabrication Plant -- 11.3 Transportation of Standard Loads -- 11.4 Transportation of Heavy Vessels -- 11.4.1 Handling heavy vessels using specialty cranes -- 11.4.2 Shipping by truck -- 11.4.3 Shipping by rail -- 11.4.4 Shipping by barge or ship -- 11.4.5 Shipping by air -- 11.5 Summary -- Chapter 12 ASME Code Compliance and Quality Control System -- 12.1 Need for ASME Code Compliance -- 12.2 What the ASME Code Provides -- 12.3 Fabrication in Accordance with the ASME Code -- 12.4 ASME Code Stamping -- 12.4.1 Design calculations -- 12.4.2 Fabrication drawings -- 12.4.3 Material mill test reports -- 12.4.4 WPS for the vessel welds -- 12.4.5 Records of nondestructive (NDE) examination -- 12.4.6 Record of PWHT -- 12.4.7 Record of hydrotesting -- 12.4.8 Manufacturer's Data Report, U-1 Form -- 12.4.9 Manufacturer's Partial Data Report, U-2 form -- 12.4.10 Name plate -- 12.5 Authorized Inspector and Authorized Inspection Agency -- 12.6 Quality Control System for Fabrication -- 12.6.1 Organizational chart -- 12.6.2 Authority and responsibility -- 12.6.3 Quality control system -- 12.6.4 Design and drawing control -- 12.6.5 Material

control -- 12.6.6 Production control -- 12.6.7 Inspection -- 12.6.8
Hydrostatic and pneumatic testing -- 12.6.9 Code stamping -- 12.6.10
Discrepancies and nonconformances -- 12.6.11 Welding -- 12.6.12
Nondestructive examination -- 12.6.13 Heat treatment control --
12.6.14 Calibration of measuring and test equipment -- 12.6.15
Records retention -- 12.6.16 Handling, storage, and shipping.
12.7 Additional Stamps Required for Pressure Vessels.
