

1. Record Nr.	UNINA9910699546303321
Titolo	Pipe support anchors installed improperly [[electronic resource]]
Pubbl/distr/stampa	Washington, DC : , : U.S. Nuclear Regulatory Commission, Office of Nuclear Reactor Regulation : , : U.S. Nuclear Regulatory Commission, Office of Nuclear Material Safety and Safeguards : , : U.S. Nuclear Regulatory Commission, Office of New Reactors, , [2010]
Descrizione fisica	1 online resource (4 pages)
Collana	NRC information notice ; ; 2010-01
Soggetti	Nuclear power plants - Piping
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	Title from PDF title screen (viewed on Aug. 23, 2010). "March 1, 2010." "ML090830184."