

1. Record Nr.	UNINA9910701779203321
Autore	Piascik Robert S
Titolo	Space Transportation System (STS)-133/external tank (ET)-137 intertank (IT) stringer cracking issue and repair assessment [[electronic resource]] : proximate cause determination and material characterization study / / Robert S. Piascik
Pubbl/distr/stampa	Hampton, Va. : , : National Aeronautics and Space Administration, Langley Research Center, , [2011]
Descrizione fisica	1 online resource (152 pages) : color illustrations
Collana	NASA/TM ; ; 2011-217318
Soggetti	Characterization Cracks External tanks Mechanical properties Space transportation system Stringers Discovery (Orbiter) Fabrication
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	Title from title screen (viewed on May 15, 2012). "December 2011."
Nota di bibliografia	Includes bibliographical references (page 38).