

1. Record Nr.	UNINA9910702475403321
Titolo	Weakness in emergency operating procedures found as result of steam generator tube rupture
Pubbl/distr/stampa	Washington, D.C. : , : United States Nuclear Regulatory Commission, Office of Nuclear Reactor Regulation, , [1993]
Descrizione fisica	1 online resource
Collana	NRC information notice ; ; 93-56
Soggetti	Nuclear power plants - Piping - Defects - United States Steam-pipes - Cracking Nuclear power plants - United States - Safety measures
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	Title from title screen (viewed Jan. 9, 2013). "July 22, 1993."