

1. Record Nr.	UNINA9910707851403321
Autore	Arroyo R.
Titolo	Assessment of RELAP5/MOD2 against a pressurizer spray valve inadvertent fully opening transient and recovery by natural circulation in Jose Cabrera nuclear station / / prepared by R. Arroyo, L. Rebollo
Pubbl/distr/stampa	Washington, DC : , : Office of Nuclear Regulatory Research, U.S. Nuclear Regulatory Commission, , June 1993
Descrizione fisica	1 online resource (xi, 44, 60 unnumbered pages) : illustrations
Collana	International agreement report ; ; NUREG/IA-0124
Soggetti	Pressurized water reactors - Accidents - Computer simulation Nuclear reactor accidents - Spain - Computer simulation
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	"Union Electrica Fenosa." "June 1993." "Prepared as part of the Agreement on Research Participation and Technical Exchange under the International Thermal-Hydraulic Code Assessment and Application Program (ICAP)." "ICSP-JC-SPR-R"--Bibliographic data sheet.
Nota di bibliografia	Includes bibliographical references (pages 43-44).