

1. Record Nr.	UNINA9910708469803321
Autore	Reventos F.
Titolo	Assessment of a pressurizer spray valve faulty opening transient at Asco Nuclear Power Plant with RELAP5/MOD2 // F. Reventos [and three others]
Pubbl/distr/stampa	Washington, DC : , : Office of Nuclear Regulatory Research, U.S. Nuclear Regulatory Commission, , December 1993
Descrizione fisica	1 online resource (ix, 30, 18 unnumbered pages) : illustrations
Collana	International agreement report ; ; NUREG/IA-0121
Soggetti	Nuclear power plants - Piping - Valves - Accidents - Spain - Computer simulation Nuclear power plants - Accidents - Spain - Computer simulation
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	"ICSP-AS-SPR-R." "Asociacion Nuclear Asco." "December 1993." "Prepared as part of the Agreement on Research Participation and Technical Exchange under the International Thermal-Hydraulic Code Assessment and Application Program (ICAP)."
Nota di bibliografia	Includes bibliographical references (page 17).