

1. Record Nr.	UNINA9910715020503321
Titolo	Cracking in boiling-water-reactor Mark I and Mark II containments caused by failure of the inerting system
Pubbl/distr/stampa	Washington, D.C. : , : United States Nuclear Regulatory Commission, Office of Inspection and Enforcement, , 1985
Descrizione fisica	1 online resource
Collana	Information notice ; ; no. 85-99
Soggetti	Boiling water reactors - Cracking Nuclear power plants - Safety measures
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	"December 31, 1985."