

1. Record Nr.	UNINA9910715119303321
Titolo	Failure of low pressure safety injection pump due to seal problems
Pubbl/distr/stampa	Washington, D.C. : , : United States Nuclear Regulatory Commission, Office of Nuclear Reactor Regulation, , 1987
Descrizione fisica	1 online resource
Collana	Information notice ; ; no. 87-51
Soggetti	Nuclear power plants - Equipment and supplies Pumping machinery Injectors
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	"October 13, 1987."