

1. Record Nr.	UNINA9910715213903321
Titolo	Undetected installation errors in main steam line pipe tunnel differential temperature-sensing elements at boiling water reactors
Pubbl/distr/stampa	Washington, D.C. : , : United States Nuclear Regulatory Commission, Office of Nuclear Reactor Regulation, , 1989
Descrizione fisica	1 online resource
Collana	Information notice ; ; 89-10
Soggetti	Boiling water reactors - Piping Steam-pipes
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	"January 27, 1989."