Record Nr.	UNINA9910715478803321
Titolo	Chevrolet vehicles
Pubbl/distr/stampa	Portland, Ore. : , : U.S. Department of the Interior, Bureau of Land Management, Portland Service Center, , 1969
Descrizione fisica	1 online resource (2 unnumbered pages)
Collana	Technical note / Bureau of Land Management ; ; [16]
Soggetti	Chevrolet trucks - Maintenance and repair Automobiles - United States - Maintenance and repair Automobiles - Maintenance and repair
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	"Date issued: September 1969."
	"Filing code: 1525 - P401."
	This technical note was reissued in December 1969, as technical note no. 24.
Sommario/riassunto	In response to overheating 250 and 292 cu. in. Chevrolet engines, the bureau issued this technical note of advisement for correcting the issue. Also includes instructions on insulating noise suppression condensers for 1968 and 1969 Chevrolet vehicles that are no longer under warranty. The noise suppression device for these vehicles have a high failure rate; insulating the metal attachment strap before failure will help prolong the life.

1.