

1. Record Nr.	UNINA9910779425803321
Autore	Draffin Nigel
Titolo	An introduction to fuel analysis [[electronic resource] /] / by Nigel Draffin
Pubbl/distr/stampa	Adderbury, : Petrosport, 2009
ISBN	1-908663-10-3 1-299-19065-0
Descrizione fisica	1 online resource (117 p.)
Soggetti	Fuel - Analysis Fuel - Testing
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	Includes index.
Nota di contenuto	<p>""Cover""; ""Dedication""; ""Foreword""; ""Preface""; ""About the author""; ""Acknowledgements""; ""Contents""; ""List of Tables and Figures""; ""Figure 1.Ships officer using hydrometer""; ""Photograph courtesy of Shell Photographic Unit""; ""Figure 2. Example text of a typical analysis report""; ""Figure 3.Table of standard prefixes for the SI units of measure""; ""Figure 4. Bunkering facilities in Colombo in 1951, before bunker quality became an issue""; ""Photograph courtesy of the Shell Photographic Unit. Taken by Derrick Knight.""</p> <p>""Figure 5. Summary table of principal grades""""Figure 6.Extract from ISO 8217 (E) 2005 Residual fuel""; ""Figure 7.Extract from ISO 8217 (E) 2005 Distillate fuel""; ""Figure 8. Asphaltenic sludge in a purifier (outside of bowl)""; ""Photograph courtesy of Petrosport Ltd""; ""Figure 9. Asphaltenic sludge in a purifier (inside of bowl)""; ""Photograph courtesy of Petrosport Ltd""; ""Figure 10.a€?Chart showing typical variations in Estimated Cetane Number (ECN) for a given value of CCAI""; ""Chart courtesy of Fueltec Solutions AS""</p> <p>""Figure 11. Fuel pump plunger damaged by organic acid""""Photograph courtesy of Bunker Claims International""; ""Figure 12. How not to take a spot sample""; ""Photograph courtesy of Petrosport Ltd""; ""Figure 13. Comparison between drip and automatic sampler""; ""Figure 14. Drip sampler and cubitainer in use""; ""Photograph courtesy of Lloyd's Register""; ""Figure 15.Drip sampler and cubitainer""; ""Photograph</p>

courtesy of Maritec Pte Ltd"; ""Figure 16. Sample bottle and seal"";  
""Photograph courtesy of DnVPS""; ""Figure 17. Sample label""  
""Photograph courtesy of Lintec Testing Services Ltd""""Figure 18.  
Sealed sample""; ""Photograph courtesy of Kittiwake Developments  
Ltd""; ""Figure 19. Digital density meter""; ""Photograph courtesy of  
Inpechem Inspectors B.V.""; ""Figure 20. Digital density test diagram"";  
""Figure 21. Density table""; ""Figure 22. Operation of an automatic  
viscometer""; ""Photograph courtesy of Lintec Testing Services Ltd"";  
""Figure 23. Ostwald type capillary viscometer.""; ""Figure 24. Viscosity  
table""; ""Figure 25. Water (H<sub>2</sub>O) table""; ""Figure 26. Carbon residue  
table""  
""Figure 27. Sulphur (S) table""""Figure 28. Total sediment test  
equipment in use""; ""Photograph courtesy of Lintec Testing Services  
Ltd""; ""Figure 29. Total sediment table""; ""Figure 30. Examples of  
Rating Numbers of Typical Spots""; ""Spot examples courtesy of Intertec  
OCA ""; ""Figure 31. Ashing a sample""; ""Photograph courtesy of  
DnVPS""; ""Figure 32. Ash table""; ""Figure 33. ICP spectrometer "";  
""Photograph courtesy of Inpechem Inspectors B.V.""; ""Figure 34.  
Schematic of an ICP system""; ""Figure 35. Determination of metals by  
Atomic Absorption Chromatography""  
""Photograph courtesy of Inpechem Inspectors B.V.""

---