

| | |
|-------------------------|---|
| 1. Record Nr. | UNINA9910816134003321 |
| Autore | Draffin Nigel |
| Titolo | An introduction to fuel analysis [[electronic resource] /] by Nigel Draffin |
| Pubbl/distr/stampa | Adderbury, : Petrosport, 2009 |
| ISBN | 1-908663-10-3 1-299-19065-0 |
| Descrizione fisica | 1 online resource (117 p.) |
| Soggetti | Fuel - Analysis Fuel - Testing |
| Lingua di pubblicazione | Inglese |
| Formato | Materiale a stampa |
| Livello bibliografico | Monografia |
| Note generali | Includes index. |
| Nota di contenuto | <p>""Cover""; ""Dedication""; ""Foreword""; ""Preface""; ""About the author""; ""Acknowledgements""; ""Contents""; ""List of Tables and Figures""; ""Figure 1. Ships officer using hydrometer""; ""Photograph courtesy of Shell Photographic Unit""; ""Figure 2. Example text of a typical analysis report""; ""Figure 3. Table of standard prefixes for the SI units of measure""; ""Figure 4. Bunkering facilities in Colombo in 1951, before bunker quality became an issue""; ""Photograph courtesy of the Shell Photographic Unit. Taken by Derrick Knight."" ""Figure 5. Summary table of principal grades""""Figure 6. Extract from ISO 8217 (E) 2005 Residual fuel""; ""Figure 7. Extract from ISO 8217 (E) 2005 Distillate fuel""; ""Figure 8. Asphaltenic sludge in a purifier (outside of bowl)""; ""Photograph courtesy of Petrosport Ltd""; ""Figure 9. Asphaltenic sludge in a purifier (inside of bowl)""; ""Photograph courtesy of Petrosport Ltd""; ""Figure 10.a€?Chart showing typical variations in Estimated Cetane Number (ECN) for a given value of CCAI""; ""Chart courtesy of Fueltec Solutions AS"" ""Figure 11. Fuel pump plunger damaged by organic acid""""Photograph courtesy of Bunker Claims International""; ""Figure 12. How not to take a spot sample""; ""Photograph courtesy of Petrosport Ltd""; ""Figure 13. Comparison between drip and automatic sampler""; ""Figure 14. Drip sampler and cubitainer in use""; ""Photograph courtesy of Lloyd's Register""; ""Figure 15. Drip sampler and cubitainer""; ""Photograph</p> |

courtesy of Maritec Pte Ltd""; ""Figure 16. Sample bottle and seal"";
""Photograph courtesy of DnVPS""; ""Figure 17. Sample label""
""Photograph courtesy of Lintec Testing Services Ltd""""Figure 18.
Sealed sample""; ""Photograph courtesy of Kittiwake Developments
Ltd""; ""Figure 19. Digital density meter""; ""Photograph courtesy of
Inpechem Inspectors B.V.""; ""Figure 20. Digital density test diagram"";
""Figure 21. Density table""; ""Figure 22. Operation of an automatic
viscometer""; ""Photograph courtesy of Lintec Testing Services Ltd"";
""Figure 23. Ostwald type capillary viscometer.""; ""Figure 24. Viscosity
table""; ""Figure 25. Water (H₂O) table""; ""Figure 26. Carbon residue
table""
""Figure 27. Sulphur (S) table""""Figure 28. Total sediment test
equipment in use""; ""Photograph courtesy of Lintec Testing Services
Ltd""; ""Figure 29. Total sediment table""; ""Figure 30. Examples of
Rating Numbers of Typical Spots""; ""Spot examples courtesy of Intertec
OCA ""; ""Figure 31. Ashing a sample""; ""Photograph courtesy of
DnVPS""; ""Figure 32. Ash table""; ""Figure 33. ICP spectrometer "";
""Photograph courtesy of Inpechem Inspectors B.V.""; ""Figure 34.
Schematic of an ICP system""; ""Figure 35. Determination of metals by
Atomic Absorption Chromatography""
""Photograph courtesy of Inpechem Inspectors B.V.""
