

1. Record Nr.	UNISA996478972703316
Autore	Eckhoff Rolf K
Titolo	Explosion hazards in the process industries // Rolf K. Eckhoff
Pubbl/distr/stampa	Houston, TX : , : Gulf Publishing Company, , [2005] ©2005
ISBN	0-12-803274-X 0-12-799972-8 1-59124-968-6
Descrizione fisica	1 online resource (451 p.)
Disciplina	604.7
Soggetti	Explosives - Safety measures Hazardous substances - Accidents - Prevention Explosions
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	Description based upon print version of record.
Nota di bibliografia	Includes bibliographical references (pages 409-428) and index.
Nota di contenuto	Front Cover; Explosion Hazards in the Process Industries; Copyright Page; Dedication; Table of Contents; Preface; About the Author; Chapter 1. Introduction; 1.1 Process Safety-A Persistent Challenge to Educators; 1.2 What Is an Explosion?; 1.3 Accidental Explosions-A Real Hazard in the Process Industries; 1.4 Basic Differences in How and Where Explosive Gas, Spray/Mist, and Dust Clouds Are Likely to Be Generated; 1.5 European Union Definition of Explosive Atmospheres; 1.6 The "Human Factor"; Chapter 2. Gas and Vapor Cloud Explosions; 2.1 Combustion of Gases and Vapors 2.2 Ignition of Premixed Gas/Vapor and Air 2.3 Case Histories of Accidental Gas/Vapor Cloud Explosions; 2.4 Means of Preventing and Mitigating Gas/Vapor Explosions in the Process Industries; Chapter 3. Explosions in Clouds of Liquid Droplets in Air (Spray/Mist); 3.1 Introduction; 3.2 Generation of Clouds Liquid Droplets in Air (Spray/Mist); 3.3 Combustion of Clouds of Liquid Droplets in Air (Spray/Mist); 3.4 Ignition of Clouds of Liquid Droplets in Air (Spray/Mist); 3.5 Case Histories of Spray/Mist Explosions 3.6 Means of Preventing and Mitigating Spray/Mist Explosions in the Process Industries Chapter 4. Gas and Dust Explosions Caused by

Smoldering Combustion in Powder Layers and Deposits; 4.1 Combustion Velocities/Rates in Powder Layers/ Deposits; 4.2 Initiation of Combustion in Powder/Dust Layers and Deposits; 4.3 Explosion Initiation Processes by Smoldering/Glowing Material; 4.4 Case Histories of Accidental Smoldering Combustion in Silos, Resulting in Gas Explosions, and Adopted Extinction Procedures; 4.5 Measures for Preventing Excessive Self-Heating in Silos; Chapter 5. Dust Explosions 5.1 What is a Dust Explosion? 5.2 Combustion of Dust Clouds in Air; 5.3 Ignition of Dust Clouds in Air; 5.4 Case Histories of Dust Explosions; 5.5 Means of Preventing and Mitigating Dust Explosions in the Process Industries; Chapter 6. Explosives, Pyrotechnics, and Propellants; 6.1 Chemical Composition of Some Explosives; 6.2 Combustion Propagation in Explosives/Pyrotechnics/ Propellants; 6.3 Ignition/Initiation of Explosives/Pyrotechnics/ Propellants; 6.4 Case Histories of Accidental Explosives/Pyrotechnics/ Propellants Explosions 6.5 Measures for Preventing and Mitigating Accidental Explosions of Explosives, Propellants, and Pyrotechnics Chapter 7. Design of Electrical Apparatuses for Hazardous Areas; 7.1 Classification of Hazardous Areas; 7.2 Basic Design Concepts for Electrical Apparatus; Chapter 8. Outline of Methods for Hazard and Risk Analysis; 8.1 Introduction; 8.2 Hazard Surveys or Inventories; 8.3 Hazard and Operability Studies (HAZOP) and Failure Modes and Effects Analysis (FMEA); 8.4 Analysis of Systems Reliability by Fault Tree Analysis; 8.5 Quantitative Risk Analysis by Event Tree Analysis 8.6 Safety Audits

Sommario/riassunto

Explosions in the process industries injure or kill hundreds, if not thousands, of workers every year. They occur in process plants, refineries, platforms and pipelines all over the world. Millions of dollars are spent repairing damages, replacing equipment and rebuilding facilities in the wake of this destruction. This book explores different types of explosions that can occur in a facility and the necessary steps to guard against them. A clear set of preventative measures, rules and standards combine to make this book a convenient guide to real-world applications. Additional t
