

1. Record Nr.	UNINA9910485590903321
Autore	Azevedo Antonio C.
Titolo	Diagnostic of concrete samples affected by internal swelling reactions / / Antonio C. Azevedo [and five others]
Pubbl/distr/stampa	Cham, Switzerland : , : Springer, , [2021] ©2021
ISBN	3-030-76497-4
Descrizione fisica	1 online resource (82 pages)
Collana	Building Pathology and Rehabilitation ; ; Volume 21
Disciplina	620.136
Soggetti	Concrete - Expansion and contraction Concrete - Testing
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Nota di contenuto	Intro -- Preface -- Contents -- 1 Introduction -- 1.1 Motivation -- 1.2 Objectives -- 2 State-of-the-Art -- 2.1 Introduction -- 2.2 Examples of Internal Swelling Reactions on Pile Cap Blocks -- 2.3 Mechanical Properties -- 2.3.1 Compressive Strength -- 2.3.2 Static Modulus of Elasticity -- 2.3.3 Dynamic Modulus of Elasticity -- 2.4 Concrete Durability Aspects-Concepts and Tests -- 2.4.1 Gas Permeability (K) -- 2.4.2 Mercury Intrusion Porosimetry (MIP) and Porosity () -- 2.5 Physical-Chemical Analysis -- 2.5.1 Scanning Electron Microscopy (SEM) -- 2.5.2 X-Ray Diffraction (XRD) -- 2.5.3 Raman Spectroscopy -- 2.5.4 Thermogravimetric Analysis (TGA) -- 3 Methodology -- 3.1 Introduction -- 3.2 Mechanical Properties -- 3.2.1 Compressive Strength -- 3.2.2 Static Modulus of Elasticity -- 3.2.3 Dynamic Modulus of Elasticity -- 3.3 Transfer Properties -- 3.3.1 Gas Permeability (K) -- 3.3.2 Apparent Porosity () -- 3.3.3 Mercury Intrusion Porosimetry (MIP) -- 3.4 Physical-Chemical Analysis -- 3.4.1 Scanning Electron Microscopy (SEM) -- 3.4.2 X-Ray Diffraction (XRD) -- 3.4.3 Raman Spectroscopy -- 3.4.4 Thermogravimetric Analysis (TGA) -- 4 Results and Discussion -- 4.1 Introduction -- 4.2 Results of the Tests Hired by the Building Owners -- 4.3 Results of the Tests Performed -- 4.3.1 Visual Inspection -- 4.3.2 Mechanical Properties -- 4.3.2.1 Compressive Strength -- 4.3.2.2 Static Modulus of Elasticity -- 4.3.2.3 Dynamic Modulus of Elasticity -- 4.4 Transfer Properties --

4.4.1 Gas Permeability (K) -- 4.4.2 Apparent Porosity () -- 4.5
Physical-Chemical Analysis -- 4.5.1 Scanning Electron Microscopy
(SEM) -- 4.5.2 X-Ray Diffraction (XRD) -- 4.5.3 Raman Spectroscopy --
4.6 Summary of Laboratory Test Results -- 6 Correction to: Diagnostic
of Concrete Samples Affected by Internal Swelling Reactions.
Correction to: A. C. Azevedo et al., Diagnostic of Concrete Samples
Affected by Internal Swelling Reactions, Building Pathology and
Rehabilitation 21, <https://doi.org/10.1007/978-3-030-76497-5> -- 5
Conclusions -- 5.1 Suggestions for Future Works -- Bibliography.
