

1. Record Nr.	UNINA9910697081503321
Autore	Grendahl Scott
Titolo	Failure analysis of a cracked CH-47 swashplate rotating ring, S/N BCW-1379 [[electronic resource] /] / Scott Grendahl, Russell Yocum
Pubbl/distr/stampa	Aberdeen Proving Ground, MD : , : Army Research Laboratory, , [2006]
Descrizione fisica	1 online resource (iv, 22 pages) : color illustrations
Collana	ARL-TR ; ; 3826
Altri autori (Persone)	YocumRussell
Soggetti	Chinook (Military transport helicopter) - Evaluation Chinook (Military transport helicopter) - Parts - Cracking - Evaluation Chinook (Military transport helicopter) - Accidents - United States - Prevention Metals - Fatigue - Testing Metals - Cracking - Evaluation
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	Title from PDF t.p. (viewed June 14, 2010). "June 2006."