

1. Record Nr.	UNINA9910697081603321
Autore	Grendahl Scott
Titolo	Failure analysis of OH-58 Kiowa Warrior drive gear shafts [[electronic resource] /] / Scott Grendahl, Victor Champagne, and Dan Snoha ; prepared by U.S. Army Research Laboratory, Weapons and Materials Research Directorate for U.S. Army Research, Development, and Engineering Command, Aviation Engineering Directorate, Propulsion Division
Pubbl/distr/stampa	Aberdeen Proving Ground, MD : , : Army Research Laboratory, , [2006]
Descrizione fisica	1 online resource (viii, 50 pages) : color illustrations
Collana	ARL-TR ; ; 3827
Altri autori (Persone)	ChampagneVictor SnohaDan
Soggetti	Armed OH-58D Kiowa Warrior (Observation helicopter) - Evaluation Armed OH-58D Kiowa Warrior (Observation helicopter) - Parts - Fractures - Evaluation Armed OH-58D Kiowa Warrior (Observation helicopter) - Accidents - United States - Prevention Metals - Fatigue - Testing Metals - Fractures - Evaluation
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	Title from PDF t.p. (viewed June 14, 2010). "June 2006."