

1. Record Nr.	UNINA9910715226503321
Autore	Peter Kathy D.
Titolo	Hydrogeologic characteristics of the Lee Acres Landfill Area, San Juan County, New Mexico // by Kathy D. Peter, Robert A. Williams, and Kenneth W. King ; prepared in cooperation with the U.S. Bureau of Land Management
Pubbl/distr/stampa	Albuquerque, New Mexico : , : U.S. Geological Survey, , 1987
Descrizione fisica	1 online resource (v, 69 pages) : illustrations, maps
Collana	Water-resources investigations report ; ; 87-4246
Soggetti	Fills (Earthwork) - New Mexico - San Juan County Groundwater - New Mexico - San Juan County Geology - New Mexico - San Juan County Water quality - New Mexico - San Juan County Hazardous wastes - New Mexico - San Juan County Fills (Earthwork) Geology Groundwater Hazardous wastes Water quality New Mexico San Juan County
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Nota di bibliografia	Includes bibliographical references (pages 40-41).