

1. Record Nr.	UNINA9910716015303321
Autore	Anderholm Scott K.
Titolo	Water-quality assessment of the Rio Grande Valley, Colorado, New Mexico, and Texas : shallow ground-water quality of a land-use area in the San Luis Valley, south-central Colorado, 1993 / / by Scott K. Anderholm
Pubbl/distr/stampa	Albuquerque, New Mexico : , : U.S. Geological Survey, , 1996
Descrizione fisica	1 online resource (ix, 94 pages) : illustrations, maps
Collana	Water-resources investigations report ; ; 96-4144
Soggetti	Groundwater - Quality - San Luis Valley (Colo. and N.M.) Groundwater - Pollution - San Luis Valley (Colo. and N.M.) Water quality - San Luis Valley (Colo. and N.M.) Water quality - Rio Grande Watershed (Colo.-Mexico and Tex.) Groundwater - Pollution Groundwater - Quality Water quality North America Rio Grande Watershed United States San Luis Valley
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Note generali	"National Water-Quality Assessment Program."
Nota di bibliografia	Includes bibliographical references (pages 61-64).