

1. Record Nr.	UNINA9911007001803321
Autore	Embankments Dams, and Slopes Technical Committee
Titolo	Highway 1 Rat Creek Embankment Failure : 2021 Reconnaissance and Analysis
Pubbl/distr/stampa	Reston : , : American Society of Civil Engineers, , 2023 ©2023
ISBN	1-5231-5531-0 0-7844-8457-0
Edizione	[1st ed.]
Descrizione fisica	1 online resource (129 pages)
Collana	Geotechnical Special Publications ; ; v.337
Altri autori (Persone)	BluntsParker FisherReid GregoryPhillip HuangJhih-Rou JohnsonKenneth A KozaciOzgur LindemanJustin ManousakisJohn SitarNicholas
Disciplina	627.8
Soggetti	Dams - Design and construction Dam failures
Lingua di pubblicazione	Inglese
Formato	Materiale a stampa
Livello bibliografico	Monografia
Nota di contenuto	Cover -- Half Title -- Title Page -- Copyright Page -- Contents -- Preface -- List of Participants and Authors -- Acknowledgments -- List of Figures -- List of Tables -- Chapter 1 : Executive Summary -- Chapter 2 : Brief Description of the Performance of Highway 1 System during the January 27 to 28, 2021, Precipitation Event -- 2.1 Highway 1 System Performance -- 2.2 Highway 1 Failure at the Rat Creek Drainage Crossin -- Chapter 3 : Geographic and Geologic Setting -- 3.1 Rat Creek Geology -- References -- Chapter 4 : Brief Big Sur Highway 1 History -- 4.1 Big Sur Highway 1 History as a System -- 4.2 Rat Creek Section History and Performance -- References -- Chapter 5 : Data Collection Activities -- 5.1 Prefailure Data and

Geometries -- 5.2 February 25, 2021, Site Activities -- 5.2.1
Terrestrial Light Detection and Ranging Acquisition -- 5.2.2 Exposure
Mapping and Sampling -- 5.2.3 Radiocarbon Dating of Exposure
Samples -- 5.3 Satellite-based Assessments -- References --
Chapter 6 : 2020 Dolan Fire -- References -- Chapter 7 : Climate and
Precipitation -- 7.1 General Climate and Precipitation History of
Big Sur, California -- 7.2 January 26 to 28, 2021, Precipitation Event
-- References -- Chapter 8 : Tree Debris Dam Formation and Breach
-- Chapter 9 : Debris Flow -- 9.1 Photographic Record along the
Debris Flow Path at Rat Creek -- Chapter 10 : Upstream Collection
Basin and Debris Volumes -- 10.1 Size of Upstream Collection Basin
-- 10.2 Calculation of the Amount of Water Reaching Highway 1 --
Reference -- Chapter 11 : Overtopping of Highway 1 and Embankment
Erosion -- Chapter 12 : 2021 Rat Creek Roadway Repair -- References
-- Chapter 13 : Summary and Recommendations -- Index.

Sommario/riassunto

GSP 337 provides an overview of the reconnaissance and analysis done
of the embankment failure caused by Rat Creek onto Highway 1 in
Northern California.
